



1/17

FIG. 1




2/17

FIG. 2




3/17

FIG. 3



**FIG. 4**



5/17

FIG. 5A






FIG. 5B




TEMPERATURE/BIAS DEPENDENCE

FIG. 5C



7/17

FIG. 6



8/17

FIG. 7A





FIG. 7B



9/17

FIG. 7C






FIG. 7D




10/17

FIG. 8



11/17

FIG. 9



12/17

FIG. 10





FIG. 11



13/17

FIG. 12




FIG. 13





FIG. 14



15/17

FIG. 15B





FIG. 15A



16/17

FIG. 16




FIG. 17





FIG. 18



17/17

FIG. 19

